

2010-10-29 Friday Morning Notes

Thursday, October 28, 2010

4:34 PM

On-call

- Wednesday and Thursday: Vladimir Nagaslaev
- Friday: Keith Gollwitzer
- Saturday: Steve Werkema
- Sunday: Jim Morgan

Stacking

- Looking into issues
 - The 204 permit was pulled a couple of times on AP1 line vertical trims VT101 and VT11A.
 - BPM downstream of the new vacuum window behaves differently. This was causing the overthruer to have problems with correcting the orbit.
 - M:Tor109 reads too high.
- We have good BPM coverage in the AP1 so we were able to mask BPM108 in both planes and the overthruer was able resume normal corrections.
 - It was found that the BPM has a large noise spike from sweeping. Moving sweeping timing does not change the BPM position.
 - The BPM might be able to be brought back to normal operation by the addition of a band pass filter. This is possible since BPM108 only is 53MHz. If it also were needed at 2.5MHz for transfers, this wouldn't work.
- M:Tor109 is reading 18% too high. Moving sweeping timing either direction reduces this by half.
- Stacking numbers: \$29-only TLG with a 2.6 second cycle time.
 - $\langle \text{stacking rate} \rangle = 26.6 \text{ mA/hr}$
 - $\langle \text{production} \rangle = 22.4 \text{ pbars/Mp}$
 - $\langle \text{POT} \rangle = 8.22 \text{ Tp}$
- NuMI comes back online on Monday morning at 10am. At that point we go back to a normal 2.2 second \$23 TLG.
 - Shot setup timelines for \$29s are currently at 2.4 seconds and will need to get moved to 2.2 seconds on Monday.

Transfers

- Unstacked 621E10 in 64 transfers over 19 sets
- $\langle \text{efficiency} \rangle = 95\%$
- But 96.6% if take away big transfers

Requests

- Broken debuncher momentum preamp in the tunnel.
- Blower D:Q907 and D:Q909

Numbers

- Daily
 - Stacking
 - Pbars stacked: 552.60 E10
 - Time stacking: 23.10 Hr
 - Average stacking rate: 23.92 E10/Hr

- Uptime
 - Number of pulses while in stacking mode: 31036
 - Number of pulses with beam: 29570
 - Fraction of up pulses was: 95.28%
- The uptime's effect on the stacking numbers
 - Corrected time stacking: 22.01 Hr
 - Possible average stacking rate: 25.11 E10/Hr
 - Could have stacked: 580.00 E10/Hr
- Recycler Transfers
 - Pbars sent to the Recycler: 659.32 E10
 - Number of transfers : 65
 - Number of transfer sets: 20
 - Average Number of transfer per set: 3.25
 - Time taken to shoot including reverse proton tuneup: 00.23 Hr
 - Transfer efficiency: 94.47%
- Other Info
 - Average POT : 8.20 E12
 - Average production: 22.80 pbars/E6 proton
- Weekly
 - Stacking
 - Pbars stacked: 3322.42 E10
 - Time stacking: 145.11 Hr
 - Average stacking rate: 22.90 E10/Hr
 - Uptime
 - Number of pulses while in stacking mode: 183151
 - Number of pulses with beam: 173106
 - Fraction of up pulses was: 94.52%
 - The uptime's effect on the stacking numbers
 - Corrected time stacking: 137.15 Hr
 - Possible average stacking rate: 24.22 E10/Hr
 - Could have stacked: 3515.22 E10/Hr
 - Recycler Transfers
 - Pbars sent to the Recycler: 3318.55 E10
 - Number of transfers : 373
 - Number of transfer sets: 116
 - Average Number of transfer per set: 3.22
 - Time taken to shoot including reverse proton tuneup: 01.31 Hr
 - Transfer efficiency: 95.35%
 - Other Info
 - Average POT : 8.40 E12
 - Average production: 22.84 pbars/E6 protons



Electronic Worklist:



Pbar			
ID	Requestor	Title	Location /Type
12596	Vander Meulen , David	Repair D:PH1AU2: D:PH1AU2 is dead in the tunnel. Suspect a regulator problem.	D60 Tunnel/ Stochastic Cooling
12587	Bair,	Check D:Q807, D:Q907, and D:Q909: Need to check blowers on	AP10,

	Chuck	Dynapowers D:Q807 at (AP10), D:Q907 & D:Q909 at (AP30). The blowers can seize and cause PS to trip off. We show that the blowers in these three supplies are in unknown condition. Need to examine and bypass blowers if necessary.	and AP30/ Power Supply
12567	Seifrid, Peter	Debuncher Momentum Band #3 Gain: Check for low gain in the high level parts for Debuncher Momentum Band #3.	A30 Tunnel/ Stochastic Cooling
12539	Drendel, Brian	Repair AP1 line vacuum leak: Leak check and perform permanent repair of the vacuum leak on the downstream AP1 line. The leak is believed to be inside of the shielding wall past the sweeping magnet and Tor109. The vacuum pipe goes into the shielding wall by about 2' and is difficult to get to. This job requires taking out Tor109, the sweeping magnet and equipment.	PreVault Enclosure/ Vacuum
12536	Peterson, David	A40 Fan Status Check: The A40 Circulating Fan status is bad. Check to see if it is a sensor problem or fan problem.	A40 Circ Fan/ ES&H Interlocks
12535	Gollwitzer, Keith	Inspection of PreVault: Inspection of Pbar tunnel; search for water leaks and ground water etc.	PreVault enclosure
12520	Wisner, Bernard	Repair shunt D:QS706.: The shunt has an offset current of 0.5A. This shunt normally runs at 0A. Refer to Pbar Elog at http://www-bd.fnal.gov/cgi-mach/machlog.pl?nb=pbar10&action=view&page=269&anchor=143636&hilite=14:36:36 for details.	Transport/ Power Supply
12500	Gollwitzer, Keith	Inspection of Transport: Inspection of Pbar tunnel; search for water leaks and ground water etc.	Transport enclosure
12499	Gollwitzer, Keith	Inspection of PreVault/Target: Inspection of Pbar tunnel; search for water leaks and ground water etc.	PreVault/Target enclosure
12491	Sprosty, Susan	ODH EXH FANS: QUARTERLY MAINT.PM.FOR ODH EXH FANS FESS ASSET #AP183,AP184,AP185,AP186,AP187	PBAR TUNNEL / FESS Utils
12474	Drendel, Brian	LCW Manifold Leak on A1B3: A1B3 has an LCW leak on the LCW manifold. The leak can be seen if you look at the manifold from the downstream end of the magnet. Under the 3" in the center of the manifold, there is a very slow LCW weeper coming from the threads on that connection. This is just above the small orange hose connector labeled "9."	Pbar Rings/ Water
12471	Drendel, Brian	D1Q5 LCW hose replacement: D1Q5 has a slow dripper on the fitting for the orange hose that goes to the LCW return header.	Pbar Rings/ Water
12470	Gollwitzer,	Inspection of Pbar Rings: Inspection of Pbar tunnel; search for water leaks and ground water etc.	Rings enclosure


	Keith		e
12469	Drendel , Brian	Rollaround Console Doesn't Work: Stochastic Cooling guys report that the Thinwire Ethernet rollaround cart console was not working when they tried to use it in the tunnel in the A30 region. The Thinnet repeater in the AP30 service building was power cycled, which did not fix the problem. We need the Network Guys to look at the Thinnet to see if it is operational.	Pbar Rings/ Controls
12450	Leveling, Anthony	November target air blower check: Perform periodic maintenance on target blower in November 2010. Last maintenance was on October 4.	AP0 Target Hall/ Target Station
12406	Drendel , Brian	ARF1 calibration: After changing out the Acopian +5V power supply in the ARF1 LLRF, the output of the ARF1 amplitude curve is saturated. One hour of no stacking time is needed to recalibrate the output.	AP50/ LLRF
12378	Drendel , Brian	D:EKIK Module #1 Power Supplies: D:EKIK module #1 is starting to show some timing drift. During a shutdown of a day or longer, it would be nice to open up the oil-filled thyratron tank and check the brick power supplies.	AP10 Service Building / Power Supply
12345	Vander Meulen , David	D:V4TW01 Trips: D:V4TW01 is tripping on reverse power. A bad cable was replaced in the tunnel, but the problem is in the tank, which means we have to let up vacuum. The job including vacuum pump down is a minimum of 6 hours.	D30 Tunnel/ Stochastic Cooling
12240	Sievert, Ken	Connect BV500H to A50 CIA Crate: Terminate cable and connector on valve, modify crate to accept valve status.	A50/ Vacuum
9310	Obrycki , Mark	Sled drawings/ panel schedules: Inspect breaker panels in tunnel	AP-10 tunnel/ ES&H Interlocks
Total Requests: 20			

Daily Plots








AP1 BPM at 108 is behaving differently after installation of the titanium vacuum window upstream of vt108 trim.



BV107



BV108, big signal from sweeping magnet



After masking BPMH108 and BPMV108, overthruster is behaving.

