


Machine Conditions:



Pasted from <<http://www-bdnew.fnal.gov/pbar/organizationalchart/derwent/stacking/weekly.png>>

- **Operations**
 - Stacking Monitor VSA had to be power cycled twice in two days
 - P150 during reverse proton tune-up had some strange behavior.
 - Overthruster - if behaving badly, check the BPMs. Reboot?
- **Instrumentation**
 - Tor724 - need access
 - Beamline BPM program is fixed, mostly. Stopped running when missed beam pulse.
- **Topic 3**
 - Performance reviews coming.