



- **Crew Chief Summary:**

- **Users Plot**



- **Accelerators Plot**



- **Notes from Run Coordinator:**

- Further discussion about A49H. Was not conditioned properly.
- Shortened up the store and re-conditioned.
- Store had problems going in. The feeddown failure.
- Initial was low and lifetime was sub=par
- Beam intensity was also down.

- **Machine Summaries:**

- **Linac**

- Summary:
  - LRF2 off - 10 minutes.
  - Klystron Debuncher - valve working find.
- Requests:
  - Switch over to other Kly deb. Pump.

- **Booster**

- Summary:
  - Downtime for bRF1 - all RF is up and running
  - Down in intensity due to losses, now back up.
- Requests:
  - Work on transition.

- **Main Injector**

- Summary:
  - HLRF - switch blower on RF 13 fixed.
  - Station 3 modulator fixed
  - Multibatch slipstacking on 2E
  - Experts working on 2E
- Requests:
  - continue 2E studies

- **Pbar**



- Requests:
      -
  - **DO**
    - Summary:
      - Ran well
      - Access - cean cards for central muon system
      - New store - lost 15 minutes, then ok.
    - Requests:
      -
  - **FESS**
    - Summary:
      -
    - Requests:
      -
  - **Mechanical**
    - Summary:
      - 2 failing roughers in TH.
    - Requests:
      -
  - **Other**
    - Summary:
      -
    - Requests:
      -
- **The Plan**
  - Summary:
    - Terminated in middle evening.
    - Kicker guys F17K3
    - Feeddown card change.
  - Requests:
    -