


2011-08-15 Monday Morning Notes


Monday, August 15, 2011
7:36 AM

Operational Notes


- MI-52 kicker regulation problems. Replaced glassman HVPS.
- AP2 BPMs needed to be power cycled and configuration script run
- Vertical Emittance monitor broke Saturday am
- Water main break in klystron area



Plots









Horizontal Area New	9.73	Intensity
Horizontal Area Calc	172.55	Intensity
Horizontal Sigma New	3.04	mm
Horizontal Sigma Calc	2.87	mm
Horizontal Mean	22.77	mm
Vertical Area New	10.15	Intensity
Vertical Area Calc	175.56	Intensity
Vertical Sigma New	3.03	mm
Vertical Sigma Calc	2.85	mm
Vertical Mean	7.61	mm











MI-52 kicker not following reference.



Downstream (AP50) AP2 BPMs stopped responding



MI-52 kicker improved after Glassman HVPS changeout