


Department Head: Keith Gollwitzer
Machine Conditions: Shutdown: Week 3

• Shutdown Progress



• Shutdown status

- Motor kicker stand -
- Pipe in D10 back under vacuum
- Quad BPMs - normal one pulled out. The skew Quad BPM slid downstream. No reorganization of instrumentation.
- New trim PS in A10 - need 480V
- AP50 SO cord - 100%
- AP0 SO cord - 50% done
- 4-8GHz core - Ralph and Co. have measured all cables at least 4 times. Measured fiber optic cable gives us a few nsec.

- fiber optic cable gives us a few nsec.
- AP30 tanks. Henry expected small leak in vacuum. Pressurized.
 - Debuncher quad shunts. Need 13 cards. They are not all done. 10%
 - Debuncher BPM - one more sector to go.
 - BLM calibration - 10 and 60 checked. Labels and cables. 2%
 - AP1 power supply switch - Still have to swap the cables between 105 and 109.
 - All power supplies have had their fans replaced.
 - Hall probes.
 - OTR - Not due for installation until April.
 - Testing of applications in the Linux world. Let Wally know which ones you want to test.
 - Make sure it initializes