

- **Booster/Main Injector**
 - Intensity has been lower than $8e12$ for most of week. Proton Source changed source.
 - Need to quantify Booster longitudinal emittance and how it impacts efficiency.
- **Pbar**
 - Struggling right now.
 - 2 days worth of studies. Improved vertical aperture in the Accumulator by a small amount, but did not improve horizontal.
 - The quad pickup needs to come out.
 - Would like to get back to 20mA/hr. Need to get bend bus and tunes right.
- **Dampers**
 - MI Pbar dampers.
- **Rapid Transfers**
 - Retreated. Will put changes back in one at a time after good transfer efficiencies are re-established.
 - Homework over the shutdown. Figure out how to attack this.
- After shutdown, will only meet once every two weeks.